PORTABLE HARDNESS TESTING

CV Portable Digital Hardness Tester

The Bowers CV Rangemaster Plus Hardness Tester represents an ideal solution to the problems associated with portable hardness testing. Its clear digital display, ease of use and ability to operate in all major international scales make it the most comprehensive unit of its type currently available.



Features

- Dynamic test indicator
- Large digital readout
- Hardness values in all major international scales with simple conversion facilities from one to the other
- RS232 output for connection to PC or serial printer
- Memory storage range for in excess of 400 readings
- · Statistical summary
- Integral icon facility provides operator with easy visual identification of mode in which unit is operating
- Operates in temperatures from -5°C to +35°C
- Upper and lower control limits
- Last reading recall
- Supplied with two UKAS certified test blocks, adjuster key and carrying case





RANP001	Rangemaster with UKAS certified test blocks		
RANP002	Rangemaster with factory certified test blocks		
PBS0001	Precision Bench Stand		
RAN0004	RS232 PC Connection Cable		

TECHNICAL SPECIFICATION			
Hardness Scale	Vickers Pyramid No., Brinell, Rockwell B, Rockwell C, Tensile Strength, Shore Scleroscope		
Testing Range	Vickers Pyramid No.	35-1000	
	Brinell	100-500	
	Rockwell B	30-100	
	Rockwell C	20-70	
	Tensile Strength	255-1999 N/mm≈	
	Shore Scleroscope	24-97	
Resolution	1	Vickers Pyramid No., Brinell, Tensile Strength, Shore Scleroscope	
	0.1	Rockwell B, Rockwell	
Power	9V battery or adaptor		
Output	RS-232 serial output		

Standard Delivery

- Main unit
- 2 UKAS certified test blocks
- Case
- Adjusting keys
- CV Instruments certificate
- Manual

Optional Accessories

- Bench stand
- RS-232 cable