



## Universal Centre Finder with Indicator

### Features

- Standard: Factory Standard
- Universal equipment for finding the centre of a bore or to measure the concentricity of work pieces
- Indicator always faces operator, also when spindle runs
- With double indicator for maximum accuracy
- For vertical and horizontal use
- Includes 6 touch points for internal and external measurement



### UNIVERSAL CENTRE FINDER

Code No	Description	Range - Internal (mm)	Range - External (mm)	Concentricity	Accuracy (mm)	Indicator Range (mm)
MW612-01	Centre finder	3.5-300	0-300	0.005mm	0.01	0-3